Cable changes in IX   (Before changing)

Work on June 20. 2021

(Chamber)

BF side

Feedthrough

DGS name

Cable name
CRYO16

In air cable

Port: 6
Connector: 8

IM/MN_T
EMP

Pin #9 is shorting to ground somewhere

BF PM

Port: 1
Connector: 6

BF_PM

"BF_PM" dose not
use Pin #9 originally.

Cable changes in IX   (After changing)

BF side

Feedthrough

Port: 6
Connector: 8

CRYO16 ✕

Pin #9 is shorting to ground somewhere

IM/MN_T EMP

Port: 1
Connector: 6

BF PM

BF_PM

"BF_PM" dose not use Pin #9 originally.

(Chamber)