




Adjacent pins

No.6 of leaked pin.  
The shine around the pin is a reflection  
of the filled "VACSEAL".


Before repair work



$t_1, t_2$  : Reaction time constant of adjacent pins  
 $t_3$  : Reaction time constant of No.6 of leaked pin



After repair work



START

ZERO

STOP

No leakage response of No.6 of leaked pin across the background 3.4 x 10<sup>-10</sup> Pam<sup>3</sup>/s was detected after repair work.

